

- OSC
Waiting for report/quotation from electrical contractor for test, rectification and other work highlighted in Fire Risk assessment.
Inspection and quotation required from alarm system contractor also from Fire Risk assessment.
Parish room door lock to be made fire compliant.
Flagpole halyard required (need a purchasing method like credit card).
(All above expenditure already approved).
Library kitchen hot water system to be inspected and assessed.
- High Bank car park
Rectify the fitting/support of drainage grill at entrance to car park.
(Expenditure unlikely to exceed £200)
- Doverhay Toilets
Disabled toilet, toilet roll holder damaged and requires replacement.
Honesty box surround of the non-disabled toilet has been forced open and money has been removed, rectification work required.
(All above expenditure unlikely to exceed £200)
- Seating
Charlotte's seat on Dunster steep is in need of repair (is PPC responsible?)
Two 'memorial' bench seats in cemetery require rectification/replacement (is PPC responsible?)
(Expenditure unlikely to exceed £200 if required)
- War Memorial
Waiting for a scheduled visit by company rep for appraisal and quote for work.
(Expenditure already approved).